



REPUBLIC AVIATION CORPORATION
FARMINGDALE, LONG ISLAND, NEW YORK
SERVICE DEPARTMENT

January 8, 1947

Distributor's No. 22

SERVICE BULLETIN ANNOUNCEMENT

Subject: Service Bulletin No. 1 – “Modification Firewall Terminal Block”.

Reason for Change: To prevent short circuiting of terminal studs on the firewall.
This is a C.A.A. Mandatory Change.

Airplanes Affected: Republic Serial Nos. 5 thru 174 incl. Serial nos. 175 and up have already had this change accomplished in production.

Description of Change: This change involves removing each stud from the terminal block on the firewall, enlarging the stud holes, installing a bushing and reinstalling the stud.

Parts Required: Parts required will be furnished in kits at no charge.

Labor Credit: Approximately two man-hours are required to accomplish the change. An allowance of \$3.00 will be made on each installation to cover labor costs on airplanes within the warranty period at the time the modification is accomplished. This allowance will be credited to your account for each airplane on which the change has been completed immediately on receipt of your invoice showing that the installation has been made without charge to the owner. Forward to the Service Department.

Bulletin Distribution: Service Bulletins are attached for distribution to owners as notice of this change.

Compliance Kit: Kits are being forwarded. Each kit will contain all required parts as well as a copy of the Service Bulletin.

W. H. Ehmann
Service Manager