



REPUBLIC AVIATION CORPORATION  
FARMINGDALE, LONG ISLAND, NEW YORK  
SERVICE DEPARTMENT

January 8, 1947

Distributor's No. 24

SERVICE BULLETIN ANNOUNCEMENT

Subject: Service Bulletin No. 4 – “Replacement of Aft Engine Lord Mount”.

Reason for Change: To prevent shearing of rubber bonding on conical halves of the mount resulting from static load imposed on them.

Airplanes Affected: Republic Serial Nos. 5 thru 189 incl. Serial nos. 190 and up have already had this change accomplished in production. Several airplanes within the affected group have had this recommended change accomplished since recent shipments of spare mounts have been of the new type.

Description of Change: This change involves replacement of the present Lord Mount assembly with improved type.

Parts Required: Parts required will be furnished in kits at no charge provided removed parts are promptly returned to Republic Aviation Corporation suitably marked as to serial number of airplane. Kits will be charged to your account until the removed parts are returned..

Time Required: Approximately one man-hour will be required to accomplish this change.

Bulletin Distribution: Service Bulletins are attached for distribution to owners as notice of this recommended change.

Compliance Kit: Each kit will contain all required parts as well as a copy of the Service Bulletin.

Action Necessary: On attached form please note serial numbers of airplanes in your territory affected by this modification and return promptly to the Republic Aviation Corporation, Service Department, to permit prompt shipment of required number of kits.

W. H. Ehmann  
Service Manager

FOR DISTRIBUTOR'S INFORMATION ONLY