



REPUBLIC AVIATION CORPORATION
FARMINGDALE, LONG ISLAND, NEW YORK
SERVICE DEPARTMENT

January 8, 1947

Distributor's No. 25

SERVICE BULLETIN ANNOUNCEMENT

Subject: Service Bulletin No. 5 – “Installation New Type Elevator Pulley Guard”.

Reason for Change: To provide a more definite means of preventing elevator control cable from coming off pulley.

Airplanes Affected: Republic Serial Nos. 5 thru 125 incl. Serial nos. 126 and up have already had this change accomplished in production.

Description of Change: This change involves removing elevator pulley guard forward of the control column and installing new guard in its place.

Parts Required: Parts required will be furnished in kits at no charge.

Time Required: Approximately one man-hour will be required to accomplish this change.

Bulletin Distribution: Service Bulletins are attached for distribution to owners as notice of this recommended change.

Compliance Kit: Each kit will contain all required parts as well as a copy of the Service Bulletin.

Action Necessary: On attached form please note serial numbers of airplanes in your territory affected by this modification and return promptly to the Republic Aviation Corporation, Service Department, to permit prompt shipment of required number of kits.

W. H. Ehmman
Service Manager

FOR DISTRIBUTOR'S INFORMATION ONLY