

---

---

REPUBLIC AVIATION CORPORATION  
FARMINGDALE, LONG ISLAND, NEW YORK  
SERVICE DEPARTMENT

---

February 5, 1947

DISTRIBUTORS BULLETIN No. 28

---

SERVICE BULLETIN ANNOUNCEMENT

Subject: Service Bulletin No. 7 "Installation Improved Fuel Strainer Drain".

Reason for Change:

To provide a strainer drain which is leakproof, air tight and which does not require safetying. This supersedes Distributors' Service News No. 7 and is a C.A.A. Mandatory change.

Airplanes Affected:

Republic Serial Nos. 5 thru 250 incl. Serial Nos. 251 and up have already had this change accomplished in production.

Description of Change:

This change involves removing present fuel strainer drain cock or plug and installing new drain with adapter.

Parts Required:

Parts required will be furnished in a kit at no charge.

Bulletin Distribution:

Service Bulletins are attached for distribution to owners as notice of this change.

Compliance Kit:

Kits will be forwarded. Each kit will contain all required parts as well as a copy of the Service Bulletin.

W. H. Ehmann  
Service Manager

FOR DISTRIBUTORS' INFORMATION ONLY