



REPUBLIC AVIATION CORPORATION
FARMINGDALE, LONG ISLAND, NEW YORK
SERVICE DEPARTMENT

March 31, 1947

Distributor's No. 33

SERVICE BULLETIN ANNOUNCEMENT

Subject: Service Bulletin No. 11 – “Inst. Elevator Cable Guide”.

Reason for Change: To prevent the lower elevator cable in the tail boom from catching on the elevator bob weight when cable tension is too slack permitting cables to sway. This is a mandatory change.

Airplanes Affected: Republic Serial Nos. 5 thru 500 incl. Serial Nos. 501 and up have already had this change accomplished in production.

Description of Change: This change involves disconnecting lower elevator control cable in the tail boom, installing cable guide and reconnecting cable.

Parts Required: Parts required will be furnished in kits at no charge.

Labor Credit: Approximately two man-hours are required to accomplish the change. An allowance of \$3.00 will be made on each installation to cover labor costs on airplanes within the warranty period at the time the modification is accomplished. This allowance will be credited to your account for each airplane on which the change has been completed immediately on receipt of your invoice showing that the installation has been made without charge to the owner. Forward to the Service Department.

Bulletin Distribution: Service Bulletins are attached for distribution to owners as notice of this change.

Compliance Kits: Kits are being forwarded. Each kit will contain all required parts as well as a copy of the Service Bulletin.

W. H. Ehmann
Service Manager

FOR DISTRIBUTOR'S INFORMATION ONLY