

Columbia Aircraft Services, Inc.
301 Airport Road
Bloomsburg, PA 17815

Complete Major Overhaul Lycoming TIO-540-A2B Engine, S/N L-1608-61 in accordance with Lycoming Overhaul Manual 60294-7. Overhauled Bendix S6LN-1208 Magneto, 10-349290-1, S/N A229670R & Bendix S6LN-1209 Magneto, 10-349290-1, S/N A226755 in accordance with Bendix Overhaul Manual X42001-1. All A.D.'s & Service Bulletins complied with as of 5/22/12. Test Cell Run & found Satisfactory.

SUBLET REPAIRS: 79025 Crankshaft (W.O. 163975 dtd. 4/5/11), 2 Ea. 73644 Counterweights (W.O. 163976 dtd. 4/1/11), Reground SL19340 Camshaft-S/N R46330-2 (W.O. 46330 dtd. 3/31/11), Repaired Crankcase, Casting #75205, Match #682 (WDC#103726 dtd. 4/13/11), Overhauled Romec RG9080J4A Fuel Pump, S/N D-4650 (W.O. 21911 dtd. 4/18/11, Overhauled RSA-10AD1 Servo Fuel Injector, P/N 2524163-15, S/N 39740 (W.O. 131911 dtd. 4/21/11).

White MULTI-USE 5" x 3"
Use template 5450™

Item 5450™

SUBLET REPAIRS, Continued:

Overhaul LW-12067 Controller-S/N HI0193, LW-10644 Controller-S/N IE0107, LW-12778-85 Wastegate-S/N HER0131, 406610-9020 Turbocharger-S/N ECR0172 (W.O. 42637/42638/42636/42639 with FAA 8130-3 Form); Overhaul LW-12126 Transition (W.O. 11678 dtd. 3/31/11).

Pertinent Details of the Overhaul are on file at this Agency under Work Order 024145 dtd. 3/11/11 & copy of Work Accomplished sent to Owner.


Karl E. George
FAA Repair Station #JM2R930K

Time Since New = Unknown

Time Since Major Overhaul = 0:00 Hrs.

White MULTI-USE 5" x 3"
Use template 5450™

Item 5450™

AVERY®

www.avery.com

Laser/Ink Jet

AVERY®

www.avery.com

Laser/Ink Jet