



SERVICE NEWS

AIRCOOLED MOTORS INC.

SYRACUSE 8, NEW YORK

Date: 11/6/46

No. FSN 40

SUBJECT: MOTOR MOUNT BOLTS ON 6A8-215-B8F ENGINES

In our periodic inspections, we have experienced several cases of loose motor mount bolts, especially on the two mounts opposite each other on the rear of the crankcase of the 6A8-215-B8F engine.

Our Service Bulletin #39, with periodic inspection procedures outlined, requested a check of motor mounts every 100 hours. We suggest that you check all motor mount bolts immediately upon receipt of this bulletin and then recheck after every 25 hours of operation.

We are investigating this problem and will have available new type bolt locks shortly. As soon as these locks are available, a supply will be sent to you for installation.

You may expect to hear from us again in the near future and I then meantime, please keep careful check of the tightness of all motor mount bolts.

AIRCOOLED MOTORS, INC.

A handwritten signature in cursive script that reads "F. J. Schaefer".

F. J. Schaefer
Service Engineering Manager

