



REPUBLIC AVIATION CORPORATION
FARMINGDALE, LONG ISLAND, NEW YORK
• • • SERVICE DEPARTMENT • • •

September 15, 1947

No. 46

DO NOT OVER-INFLATE SEAT BACK BLADDERS

An appreciable number of seat back bladder leaks have resulted from over-inflation due to temperature rise and high altitude, which causes expansion of the contained air. Therefore, if the bladders are pumped up to capacity there is no room for expansion and bladder failures are the ultimate result.

It is recommended that the bladders be pumped up to about one-half capacity for best service endurance. Under no circumstances should they be inflated to the point where the air in the bladders is under pressure.

W. H. Ehmann
Service Manager