


Instruction No. 2

Installation of Elevator L.H. or R.H.

Items 1078 and 1082



1. If this elevator is to be installed on Ships 1-307, the Trim Tab Rod (Item 1327), extending from the Stabilizer to which this elevator is to be attached, must be removed and the new type short flexible shaft (Item 1502) installed. This new shaft is included with this Elevator. To facilitate lubrication and easy access to the Trim Tab gear box in the rear of the Stabilizer, a hand hole has been designed as explained in the attached Seabee Service News No. 17. This hand hole will aid in installing the new short flexible shaft (Item 1502) when this elevator is used on Ships 1-307.
2. If this elevator is to be installed on Ships 308 and up, Item 1502, the short flexible shaft, is already installed on the Stabilizer and there is no interchangeability problem.