


INSTRUCTION NO. 8

ITEM 1535



Replacement Radio Filters for Seabees Nos. 480, 487 thru 636 inclusive consist of a new filter bracket, clamp and hardware and are to be installed on the engine ignition coil as shown on the attached (illustration): (See INSTRUCTION NO. 11, page 3)

Parts Required:

<u>Quan.</u>	<u>Part Number</u>	<u>Part Name</u>
3	17F82077-1	Nipple
1	17F82094-1	Bracket Assy.
1	17F82095-1	Clamp
1	17F82002-80	Wire
1	JX65A	Filter (SPRAGUE) (condenser)
1	AN365-1032	Nut
3	AN520-10-8	Screw
1	AN742-14C	Clamp
1	AN960-10	Washer
2	AN960-416L	Washer

NOTE: These parts supersede SK-17-83053-1 Filter Assembly as outlined in Service Bulletin No. 15.