



REPUBLIC AVIATION CORPORATION  
FARMINGDALE, LONG ISLAND, NEW YORK  
• • • SERVICE DEPARTMENT • • •

---

June 19, 1947

No. 34

---

### THROTTLE CONTROL CLAMP ON PORT FUEL PUMP

It is recommended that all Seabee owners check the throttle control clamp mounted on the port side of the fuel pump to insure that the throttle control casing is held rigidly. Two instances have brought to our attention where the control casing apparently took on a permanent set after a period of time and permitted the throttle control to slide back and forth, thus varying the carburetor setting in flight. If this condition is found to exist, it is advised that friction tape be wound around the control to insure that clamping action is retained. It is also suggested that this item be checked at each 25-hour inspection.

W. H. Ehmman  
Service Manager