



REPUBLIC AVIATION CORPORATION
FARMINGDALE, LONG ISLAND, NEW YORK
• • • SERVICE DEPARTMENT • • •

November 24, 1947

No. 52

DEFECTIVE FIRE EXTINGUISHERS

We have been advised by the Pyrene Manufacturing Company that due to defective material used in the production of some of their Pyrene hand extinguishers during 1946 and early part of this year, some units have proven inoperative.

Adjustment will be made after examination of any new extinguishers, which are found mechanically defective. If necessary to make any such returns we suggest you advise the Pyrene Manufacturing Company, Service Department, Newark 8, New Jersey by letter, when and how such shipments are returned.

W. H. Ehmman
Service Manager