

1. Aircraft		2. Owner	
Make	Republic	Name (As shown on registration certificate)	John R. Greeff
Model	RC-3	Address (As shown on registration certificate)	11011 Aero Lane Yelm, WA 98597
Serial No.	477		
3. For FAA Use Only			
4. Unit Identification			
Unit	Make	Model	Serial No.
AIRFRAME	(As described in Item 1 above)		
POWERPLANT			
PROPELLER			
APPLIANCE	Type		
	Manufacturer		
5. Type			
Repair	Alteration		
	X		
6. Conformity Statement			
A. Agency's Name and Address		B. Kind of Agency	
Loren Chance 14915 58th Avenue South Tukwila, WA 98168		<input checked="" type="checkbox"/> U.S. Certificated Mechanic	
		<input type="checkbox"/> Foreign Certificated Mechanic	
		<input type="checkbox"/> Certificated Repair Station	
		<input type="checkbox"/> Manufacturer	
		C. Certificate No. IA1326269	
D. I certify that the repair and/or alteration made to the unit(s) identified in item 4 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.			
Date 02-19-91		Signature of Authorized Individual <i>Loren Chance</i>	
7. Approval for Return To Service			
Pursuant to the authority given persons specified below, the unit identified in item 4 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> REJECTED			
BY	FAA Fit. Standards Inspector	Manufacturer	<input checked="" type="checkbox"/> Inspection Authorization
	FAA Designee	Repair Station	Other (Specify)
Date of Approval or Rejection 02-19-91		Certificate or Designation No. IA1326269	Signature of Authorized Individual <i>Loren Chance IA1326269</i>

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

Installation of the following STC's:

1. SA1293NW - Install Lycoming TIO540-A2C and Hartzell NC-E3YR-7LF Propeller.
2. SA823NW - Install overhead control quadrant.
3. SA391NW - Install flush fuel fillers.
4. SA393NW - Modification of main keel gusset.
5. SA392NW - Install tapered wide spray rails.
6. SA374NW - Install "IFR" instrument panel.
7. SA395NW - Reshaping of cabin aft side windows.
8. SA576NW - Install disc brake system.
9. SA575NW - Install longitudinal step kit.
10. SA613NW - Install 28V electrical system.
11. SA394NW - Install droop wingtips.

-- NOTHING FOLLOWS --

Additional Sheets Are Attached