FRANKLIN SERVICE BULLETIN



SERVICE BULLETIN

AIRCOOLED MOTORS INC.


SYRACUSE 8, NEW YORK

DATE: 11/21/46 NO. FSB 42

SUBJECT: AUTO-LITE SPARK PLUGS AS USED ON THE FRANKLIN MODELS $\underline{6A-215-B8F}$ AND $\underline{B9F}$ ENGINES IN THE REPUBLIC SEABEE

The correct Auto-Lite spark plug for the 6A8-215-B8F and B9F engines is A-4, which will be found stamped on the porcelain of the plug.

In the event you have spark plugs in your stock with the earlier identification, AH-4, and they have center electrode wire of .125" diameter, they are satisfactory for use. All future production of this model spark plug by Auto-Lite will be identified as A-4.





FRANKLIN SERVICE BULLETIN

No. 42

Date: 11/21/46

Subject: AUTO-LITE SPARK PLUGS AS USED ON THE FRANKLIN MODEL 6A8-215-B8F ENGINE IN THE REPUBLIC SEABEE

In Franklin Service Bulletin #37, information was given with reference to identification of Auto-Lite spark plugs as used in the Franklin engine in the Repubic Seabee airplane. We indicated that identification could be made by the diameter of the center electrode.

Since that time, we have been advised that identification of the correct Auto-Lite spark plug for the 6A8-215-B8F engine will be A-4, which will be found stamped on the porcelain of the plug.

In the event you have spark plugs in your stock with the earlier identification, AH-4, and they have center electrode wire of .125" diameter, they are satisfactory for use. All future production of this model spark plug by Auto-Lite will be identified as A-4.

The above is for the information of service people in identifying the correct spark plugs.

AIRCOOLED MOTORS, INC.

F. J. Schaefer

Service Engineering Manager