



REPUBLIC AVIATION CORPORATION  
FARMINGDALE, LONG ISLAND, NEW YORK  
• • • SERVICE DEPARTMENT • • •

---

JANUARY 3, 1947

No. 9

---

### INFLATION OF OLEO STRUT

When it is necessary to inflate the oleo strut of your Seabee and a mechanical compressor is not available, use a compressed air bottle with a regulator and gage. This bottle may be filled with any of the following gases:

1. Dry Compressed Air
2. Bottled Nitrogen
3. Bottled Dry CO<sub>2</sub>

CAUTION: Do Not Use Oxygen, Acetylene, or any combustible gas as a violent explosion may result.

For further information concerning servicing of the oleo strut, refer to Seabee Service News No. 3 dated November 27, 1946.

W. H. Ehmman  
Service Manager